Appendix G: 2310 Horse Stamp Church Road Basin Photo Sheets 1-10



Photo 1: Facing west at dock from east side of basin



Photo 2: Facing north at concrete pathway leading to dock



Photo 3: Facing south at concrete pathway away from dock



Photo 4: Facing north at pavilion, end of concrete pathway, and eastern access point



Photo 5: Facing west at pavilion and eastern access point



Photo 6: Facing west from pavilion at wooden dock



Photo 7: Facing west at wooden dock and western access point



Photo 8: Example of original boards vs replacement 7' boards



Photo 9: Facing north at western access point



Photo 10: Facing west at end of wooden dock, aluminum ramp, and floating dock



Photo 11: Facing west down aluminum ramp at floating dock



Photo 12: Facing east from floating dock at aluminum ramp and wooden dock





Photo 13: Facing east from floating dock at underside of wooden dock



Photo 14: Facing east at asphalt boat ramp located in the southeast corner of the basin



Photo 15: Facing north at asphalt boat ramp located in the southeast corner of the basin



Photo 16: Facing east from pavilion at basin during low tide, the asphalt boat ramp termination point can be sees in the upper right-hand corner of the photo





Photo 17: Facing west at concrete boat ramp located southwest of the basin



Photo 18: Facing south at concrete boat ramp located southwest of the basin





Photo 19: Facing north at concrete boat ramp. The wooden dock and concrete walkway can be seen in the background.



Photo 20: Facing east at the channel and concrete boat ramp

Appendix H: Historical Aerials, dating 1988-2022

Tidewater Dock

Year 1988

Google Earth

Tidewater Dock Year 1993

Google Earth

Image U.S. Geological Survey













