



Figure 1: Aerial View of Haul Out Slip at Medium Tide



Figure 2: Aerial Image of Haul Out Slip at High Tide with basic outline of Construction Plan

GA DNR

FEB 10 2017

Marsh & Shore Mgt. Program






Figure 3: Haul-Out-Slip



Figure 4: Haul Out Slip

GA DNR

FEB 10 2017

Marsh & Shore Mgt. Program





*Figure 5: Drainage Pass-Through Culvert*



*Figure 6: Haul Out Slip*

**GA DNR**

**FEB 10 2017**

Marsh & Shore Mgt. Program





Figure 7: Haul Out Slip




Figure 8: Narrow Dirt Access Path which is the safety concern

GA DNR

FEB 10 2017

Marsh & Shore Mgt. Program