

Photograph 1: Location of proposed 63' x 164' deck extension on the upstream end of Berth 2



RECEIVED AUG 01 2019

Photograph 2: Downstream view of the existing dock. Photograph taken on the western end bridge facing east.



RECEIVED AUG 01 2019

Photograph 3: Example of damaged concrete revetment to be repaired



RECEIVED AUG 01 2019



